

Syncing a Quantum Transmitter (Belly Box) to a Trackporter®


1. Start with both Trackporter and transmitter powered “OFF”.



“Off” Position




2. Press and hold the ENABLE Button **and** the WINCH CONTROL Joystick in the UP position, at the same time release the E-STOP. Keep holding for greater than ten seconds.
3. Release the winch control joystick and enable button when the Enable and Transmitter Power Indicators start blinking.



4. Rotate main power switch to the ON position. Only the Enable Indicator LED (Green) should start to blink on the Transmitter.



“On” Position



5. Press and hold the ENABLE Button until the Enable Indicator LED turns solid green and syncing is complete.

Action Manufacturing Inc.

1105 Lake Road, PO Box 620
Marshall, MN 56258
(507) 532-5940